

**From:** [Crocker, Michelle](#)  
**To:** [Johnson, Jason](#)  
**Subject:** WGS - South Pond  
**Date:** Tuesday, October 1, 2019 8:35:13 AM  
**Attachments:** [image001.png](#)

---

Jason,

As discussed, last year's inspector of the Winyah Generating Station's Coal Combustion Residual Impoundments recommended installing an engineered toe drain in the South Pond dike where a wet area was observed on the downstream slope. Due to changes in operation, this wet area has decreased in size. With future plans to close the plant, I would suggest for plant personnel to continue to monitor this area as part of their weekly inspections; however, an engineered toe drain is not needed at this time.

Mikki Crocker, PE

 Civil Projects (OC-08), 1 Riverwood Drive, Moncks Corner, SC 29461

 843.761.8000 x 4745

 [mikki.crocker@santeecooper.com](mailto:mikki.crocker@santeecooper.com)

