

From: [Tudor, Michelle](#)
To: [Bergamo, Zoe](#)
Cc: [McMakin, Ryan](#); [Mills, Richie](#)
Subject: 2018 WGS CCR Impoundment Inspection Follow Up
Date: Wednesday, January 16, 2019 3:19:14 PM

Zoe,

The 2018 Winyah Generating Station CCR Impoundment Inspection Report contained two maintenance items which were recommended to be addressed within 90 days from the date of the report. The information below details the recommendations and the condition of these items as of 1/7/2019.

-

Ash Pond A

The erosion areas on the downstream slope should be repaired within 90 days.

These areas were repaired to a satisfactory condition within 90 days.

Ash Pond B

The eroded area on the downstream slope should be filled, regraded, seeded and monitored until stabilized within 90 days.

This area was repaired to a satisfactory condition within 90 days.

Please let us know if you have any questions on the above or need any additional information.

Thank you,

Michelle Tudor