

From: [DuPre, Michael](#)
To: [Corrigan, Charles](#)
Cc: [Crocker, Michelle](#); [Bagwell, Russell](#)
Subject: Cross Repair Documentation
Date: Monday, March 21, 2022 9:47:19 AM

Chip,

Per your request to follow up on the Worley Corrective Measures at CGS, I feel that all of the areas of concern have indeed been properly addressed.

I asked Russell Bagwell, Civil Engineering Technician to visit the site with the Worley report in hand and inspect each of the noted deficient areas . Russell completed his inspection and felt all of the areas had been properly addressed. He provided supporting photos of each repaired area for my review and I concur with his assessment. It is my opinion, based on Russell's field inspection and my personal review of his supporting photos that the recommended repairs have been properly done to prevent the potential for future damage.

If you have any questions or need any additional information, please let us know.

Thanks,

Michael DuPre II, PE
Civil Projects & Dam Safety
Santee Cooper
One Riverwood Drive
Moncks Corner, SC 29461
☎: 843-761-8000 ext. 5677
✉: mdupre@santeecooper.com